

CRio Reimaging. We have the current version, connect to robot with 255.255.255.0 subnet mask.
We reimage. Now 10.15.11.2 are we.

Example robot code template is unsafe.

<http://wpilib.screenstepslive.com/s/3120/m/7913/l/79734-creating-a-robot-project>

While (1) is abysmal: things cannot be disabled.

Safety "Watchdog" is disabled.

Imaging with Black Jaguar Plugin may have enabled the Console Output automatically.

Use checkboxes instead of button/light devices. Get rid of the blue background. It will be much clearer, and much simpler to alter. The switches can be misleading.

;; CODE

'motor safety safety timer'. If it is a bad idea, why bother even showing it in the example, instead of warning about it. Why make teams do this, instead of serving it with the Simple Robot Template.

The guide gives the wrong template anyway.

Compile error on RobotDrive drive(1,2);

Compile. No directions yet for last sections.

Debugging. No Directions.

VxWorks. Exception in some Kernel task.

An issue with pid->Disable(), which worked last year. It *seems* that last season's modifications to a WPILIB file confused the linking. (compiler function mapping problem, we renamed the file and class). Fixed.

Deploying. No Directions.

;; TESTING: No problems